	P0401- 00
sub type information	EGR "A" Flow Insufficient Detected - No

- Other EGR related DTCs
- Exhaust gas recirculation valve High pressure
- EGR cooler/system blocked
- Exhaust gas recirculation valve High pressure
- EGR valve mechanical integrity
- Exhaust gas recirculation valve High pressure
- Connector is disconnected, connector pin is backed out, connector pin corrosion

- Check powertrain control module for EGR related DTCs and refer to relevant DTC index
- Exhaust gas recirculation valve High pressure
- Check EGR cooler/system for soot blockage
- Exhaust gas recirculation valve High pressure
- Check EGR valve for mechanical integrity
- Exhaust gas recirculation valve High pressure
- Inspect connectors for signs of water ingress and pins for damage and/or corrosion
- Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest