TECHNICAL BULLETIN



18 MAR 2019

© Jaguar Land Rover Limited All rights reserved.				
415-01				
SUBJECT/CONCERN:				
Audio Amplifier - Loss of Audio and Quiescent Drain				
MARKETS:				
ASIA PACIFIC; CHINA; EUROPE; JAPAN; MENA; OVERSEAS				
CONDITION SUMMARY:				
SITUATION:				
A customer may express a concern that the vehicle battery is discharged and/or a loss of sound from the audio system and parking aid system. Plug-in Hybrid Electric Vehicle (PHEV) vehicles may show a warning message indicating the Audible Vehicle Alert System				

CAUSE:

(AVAS) is not available.

Software concern with the Audio Amplifier Module (AAM). **Suggested customer concern code - JR1.**

ACTION:

Should a customer expresses a concern, follow the service procedure(s) below. This technical bulletin has been updated due to changes to the diagnostic procedure and condition summary.

TOOLS:





WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Update the Audio Amplifier Module (AAM)	86.91.47	0.2	42	LR098871

NOTE:

Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE:

CAUTION:

This procedure requires a minimum of Pathfinder 217 loaded or later.

NOTES:

- If communications cannot be established with the Audio Amplifier Module (AAM), remove fusible link FL16 (see TOPIx Electrical Information - Electrical Wiring Diagrams - Fuse and Relay Locations) from the load space junction box for a period of 5 seconds and then re-install the fusible link, this will make sure the module is automatically powered down and communications are re-established to the AAM.
- The Jaguar Land Rover (JLR) approved diagnostic equipment will read the Vehicle Identification Number (VIN) for the vehicle and automatically take the vehicle out of 'Transportation mode' if required.
- This software update to the AAM is only required where any of the following software part numbers are present in the AAM: JPLA-14C526-CH or JPLA-14C526-DJ.

Connect the JLR approved battery support unit.

- ^{2.} Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.
- ^{3.} Follow the JLR approved diagnostic equipment prompts.
 - Select 'ECU Diagnostics'.
 - Select Audio Amplifier Module [AAM].
 - Select 'Update ECU'.
 - Follow all on-screen instructions to complete the task.
- 4. If required, reset the vehicle to 'Transportation mode'.
- ^{5.} When all of the tasks are complete, exit the session.

	6.	Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit.
aGVzaGly		DisLTAQLTIwVDixOjUzOjAQLjg1MFo7MTQzLjiQNC4zNy4xNjg7U0FMRQEyQUoySkEzODcwMDc~